


Site Code: <b>MNO12</b>	Location: <b>AREA</b>	Grid Sq: <b>150/215</b>	Context Type: <b>MASONRY</b>	Context Number: <b>3416</b>
1. Materials	① BRICK (MID PURPLEY RED, HARD)			
2. Size of materials (brick: BTL in mm)	② 78mm x 68mm x 225mm			
3. Finish of stones	③ MOULDED BRICK			
4. Coursing / bond	④ BOTTOM COURSE OF HEADERS ON BED, TWO COURSES OF STRETCHERS ON BED ABOVE			
5. Form	BOTTOM COURSE IS OFFSET BY 40mm ON EAST FACE.			
6. Direction of face(s)	⑤ REPAIR TO WALL / FOUNDATION.			
7. Surface treatment	⑥ EAST / WEST			
8. Bonding material (if brick: record height of 4 courses & 4 bed joints in m)	⑦ -			
9. Dimensions of masonry as found	⑧ MORTAR (CREAMY YELLOW, HARD, FINE INCLUSIONS) 4 COURSES NOT PRESENT			
10. Other comments	⑨ 0.81m N-S, 0.64m E-W, 0.29m HIGH			
				Max Level: 10.83 m OD
				Min Level: 10.54 m OD

Stratigraphic Relationships:



Physical Relationships:

Abuts:	Abutted by:
Cut by:	

Interpretation:	<u>internal</u>	external
REPAIR TO GEORGIAN WALL DAMAGED BY THE CONSTRUCTION OF A NEW CAST IRON DRAIN PIPE		
Context same as:		

Sample No(s):	Drawing No(s): <b>3416</b> (x1)
Photo No(s): <b>—</b>	Sketch/levels overleaf: <input checked="" type="checkbox"/> Transferred to plan: <input checked="" type="checkbox"/>

Compiled by: <b>JR + MK</b>	Date: <b>26/05/15</b>	Checked by: <b>ca/10/15</b>	Tick when entered in database: <input type="checkbox"/>
--------------------------------	--------------------------	--------------------------------	---

Context Number:

3416

Level No.s 1-5

Level No.s

Level No.s

Level No.s

TBM 11.40

TBM

TBM

TBM

B/S 1.06

B/S

B/S

B/S

IH 12.46

IH

IH

IH

No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)
1	1.67	10.79	6	1.92	10.54						
2	1.63	10.83	7	1.84	10.62						
3	1.79	10.67									
4	1.69	10.77									
5	1.66	10.80									

