


Site Code: MNO12	Gr. Sq. / TP/Ty 145/255	Context Type: MASONRY	Context Number: [1126]
1. Materials	①. MID PURPLISH RED BRICK, WITH SHALLOW FROGGING, HARD BRICK.		
2. Size of materials (brick: BTL in mm)	②. 110mm x 65mm x 225mm		
3. Finish of stones	③. X1 WHOLE BRICK & X3 HALF BRICKS.		
4. Coursing / bond	④. LAY ON BED IN ROWS.		
5. Form	⑤. BRICK FLOOR		
6. Direction of face(s)	⑥. WP		
7. Bonding material (if brick: record height of 4 courses & 4 bed joints in m)	⑦. MID REDDISH BROWN, SANDY LIME MORTAR, SOFT & FINE CONSISTENCY		
8. Dimensions of masonry as found	⑧. 0.44m = N-S AXIS		
	0.20m = E-W AXIS		
9. Other comments	⑨. SOME BLACK STAINING ON SURFACE.		

Stratigraphic Relationships:



Physical Relationships:

Abuts:	Abutted by:
Cut by: [1116] MODERN CONCRETE DRAIN	

Interpretation: internal ~~external~~
BRICK FLOORING OF ROOM.
 FLOOR TRUNCATED BY MODERN CONCRETE DRAIN, SO REMAINS OF FLOOR SPLIT BETWEEN [1126] & [1125]. ALSO CUT BY PIT [1116], FILLED WITH 20th DEMOLITION WASTE.
 AS [1125], FLOOR LAYED AFTER TANKING OF WALLS, PROVIDING WATERPROOFING FOR ROOM.
 SIMILAR BLACK STAINING AS SEEN ON [1125] - LIKELY DUE TO OCCUPATION.
 FULL E-W EXTENT IF INCLUDING [1125] IS 2.45m.
 Context same as: FLOOR TRUNCATED BY CONCRETE DRAIN, SAME AS [1125]

Sample No(s):	Drawing No(s): 1126 (x 1)
Photo No(s): i377, 1381 → 1386, 1389 → 1391.	Sketch/levels overleaf: <input checked="" type="checkbox"/> Transferred to plan: <input checked="" type="checkbox"/>

Compiled by: TS	Date: 24/11/14	Checked by: a. 10/12/14.	Tick when entered in database: <input type="checkbox"/>
--------------------	-------------------	-----------------------------	---

Context Number:
1126

Level No.s
TBM 10.29
B/S 1.84
IH 12.18

Level No.s
TBM
B/S
IH

Level No.s
TBM
B/S
IH

Level No.s
TBM
B/S
IH

No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)
1	1.79	10.39									
2	1.75	10.43									
3	1.78	10.40									

