

Site Code: MNO12	Grid Square: 130/205	Context Type: TIMBER	Context Number: T100 (3097)
1 Type	① DRIVEN PILE		
2 Setting	② VERTICAL. DRIVEN INTO LOWER DEPOSIT		
3 Orientation	③ PART OF N-S REVETMENT		
4 Cross-Section	④ TRIANGULAR		
5 Condition	⑤ SLIGHTLY TRUNCATED AT TOP WITH		
6 Dimensions m/mm	SOME DAMAGE OTHERWISE GOOD. IN SITU		
7 Conversion	⑥ 2.31 m x 0.22 x 0.22m		
8 Tool Marks	⑦ QUARTERED + DE BARLED.		
9 Joints & Fittings			
10 Intentional Marks	⑧ SAW MARKS ON ALL CUT SURFACES.		
11 Surface Treatment	SLIGHTLY CURVED. POSSIBLE ADZE MARKS		
12 Other Comments	ON POINT		
13 Method & Conditions	⑨ ABUTTED BY PLANKS BEHIND BUT NO		
FIXING.	⑩ NONE.	⑪ NONE.	DEBARLED
	⑫		
	⑬ MATTOCK + SHOVEL		
Reuse	Yes:	No: <input checked="" type="checkbox"/>	Unknown:
Phases of Reuse:			
UNLIKELY. VERY EDGE OF TREE TRUNK.			

Interpretation: DRIVEN PILE HOLDING BACK PLANKING OF
TIMBER REVETMENT (3097) DRIVEN INTO LOWER
DEPOSITS TO MAKE A DEFINITE BOUNDARY ALONG
THE DITCH EDGE.

DAU

2860
1
3097
2861

Associated Timbers: 101 - 105, 116 - 119, 120 - 123, 124, 125

Context same as:

TIMBER CROSS SECTION		
Bark:		NO
Sapwood:		YES
Knotty:		YES
Straight-grained:		YES

Sample No(s):	Drawing No(s): 3097 (x2) S. 71 x 2
Photo No(s): 5425-7, 5428-13	Sketch/levels overleaf: <input checked="" type="checkbox"/> Transferred to plan: <input type="checkbox"/>

Compiled by: BSS	Date: 24/4/15	Checked by: a 3/1/15	Tick when entered in database: <input type="checkbox"/>
---------------------	------------------	-------------------------	--

Context Number:
T100 (3097)

Level No.s	Level No.s	Level No.s	Level No.s
TBM 8.00	TBM	TBM	TBM
B/S 1.43	B/S	B/S	B/S
IH 9.43	IH	IH	IH

No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)
30	1.52	7.91									
37	3.83	5.60									

