


Site Code: MND 12	Grid Square: GPI	Context Type: Cut	Context Number: 8 17
Deposit		Cut	
1. Compaction	1. UNCLEAN	1. Shape in Plan	
2. Colour	2. NONE	2. Corners	
3. Composition	3. VISIBLE FOR 1.8m IN GEOTECHNICAL	3. Dimensions	
4. Inclusions	RT	4. Break of slope - Top	
5. Dimensions	4. NOT VISIBLE	5. Sides	
6. Other Comments	5. " "	6. Break of slope - Base	
7. Method/Conditions	6. " "	7. Base	
	7. " "	8. Orientation	
	8. UNCLEAN	9. Inclination	
	9. N/A	10. Truncation	
	10. NONE	11. Other comments	
ii. VISIBLE IN GEOTECHNICAL PIT TRUNCATING TOP OF BRICK BARREL VAULT [9/14] FULL EXTENT NOT VISIBLE.			



Interpretation:

CONSTRUCTION CUT (?) POSSIBLY ASSOCIATED WITH CONSTRUCTION OF DISTRICT LINE DIRECTLY TO WEST

CUT RUNS N-S, TRUNCATING BRICK BARREL VAULT [9] / [14]. AFTER THE TOP OF THE VAULT IS TRUNCATED BY THIS EVENT IT IS BACK FILLED WITH CONCRETE (15)

TOP DEPOSIT : 13.59 MOD
 BOTTOM DEPOSIT : 13.14 MOD

Context same as:

Finds: None Pot Bone Glass Metal CBM Flint Wood Leather

Other (specify):

Sample No(s): _____ Drawing No(s): MC 2 (x 1)

Photo No(s): _____ Sketch/levels overleaf:
 Transferred to plan:

Compiled by: DE Date: 15/8/12 Checked by: _____ Tick when entered in database:

SEE SKETCH PLAN ON 6