


Site Code: MNO12	Gr. Sq. / TP / Tr: TP 2	Context Type: MASONRY	Context Number: 130
1. Materials	1: BRICK		
2. Size of materials (brick: BTL in mm)	2 220 x 100 x 65 mm		
3. Finish of stones	3 UNFROGGED DARK ORANGE RED → PURPLE RED BRICK		
4. Coursing / bond	4 UNCLEAN DUE TO MODERN TRUNCATION - APPEARS TO ALTERNATE HEADS + STRETCHERS		
5. Form	5 WALL		
6. Direction of face(s)	6 WEST EAST + WEST (EASTERN FACE TRUNCATED)		
7. Bonding material	7 DME GREE SANDY LIME MORTAR WITH COARSE LIME INCLUSIONS		
(if brick: record height of 4 courses & 4 bed joints in m)	8 3.80 m N-S x 0.35 m E-W		
8. Dimensions of masonry as found	9 TRUNC. TO 4.		
9. Other comments	HIGHEST LEVEL: 13.04		

Stratigraphic Relationships:



Physical Relationships:

Abuts: /	Abutted by: 130
Cut by: MODERN CONSTRUCTION CUT	

Interpretation:	internal	external
END WALL OF THE CASSETT. DESTROYED IN BLITZ IN 1940s. EASTERN EXTENT TRUNCATED BY MODERN CONSTRUCTION CUT. FOOT EXISTING BUILDING INSIDE (WEST FACING) FACE OF WALL COVERED IN WHITE PLASTER.		
WALL IS BELOW CONTEMPORARY GROUND LEVEL (i.e. LEVEL OF VINE STREET (54) TO EAST) AND MUST BE ASSOCIATED WITH BASEMENT OF SEMI-BASEMENTS. POORLY PRESERVED TRUNCATED BY MODERN CUT + SLIMPING INTO THIS CUT. ALSO POSSIBLY DAMAGED BY BOMBING		
Context same as:		

Sample No(s): /	Drawing No(s): P5 (x 3)
Photo No(s): /	Sketch/levels overleaf: <input checked="" type="checkbox"/> Transferred to plan: <input checked="" type="checkbox"/>

Compiled by: DE	Date: 13.09.10	Checked by: on 21/9/12	Tick when entered in database: <input type="checkbox"/>
-----------------	----------------	------------------------	---

