


Site Code: MNO12	Location: <i>C w/B</i>	Grid Sq: <i>T35/220</i>	Context Type: MASONRY	Context Number: 334
1. Materials	1. <i>IRREGULAR - RED V.S. SLIGHTLY FLECKED BRICKS</i>			
2. Size of materials (brick: BTL in mm)	2. <i>BTL 105 x 62 x 225 mm.</i>			
3. Finish of stones	3. <i>BRICKS</i>			
4. Coursing / bond	4. <i>ENGLISH.</i>			
5. Form	5. <i>WALL WITH INTERNAL ARCH OF BARREL VAULT.</i>			
6. Direction of face(s)	6. <i>EAST</i>			
7. Surface treatment	7. <i>LIMEWASH.</i>			
8. Bonding material (if brick: record height of 4 courses & 4 bed joints in m)	8. <i>LIGHT GREY LIME MORTAR WITH FINE LIME FLOCKS</i>			
9. Dimensions of masonry as found	9. <i>2.65 - N-S x ? 0.6 - THICK x 3.0 - HIGH.</i>			
10. Other comments	10. <i>OBSERVED IN W/BRIEF</i>			
			Max Level: <i>13.23 m OD</i>	
			Min Level: <i>10.23 m OD</i>	

Stratigraphic Relationships:



Physical Relationships:

Abuts:	Abutted by:
Cut by:	

Interpretation:	<input checked="" type="checkbox"/> internal	<input type="checkbox"/> external
<i>WESTERN OF VINE STREET - STREET FROM THIS WALL, EXPOSED.</i>		
<i>INTERNAL FACE OF WALL DURING WATCHING BRIEF ON PILE PROBING.</i>		
<i>SURVEYED BY ISJ.</i>		
<i>BARREL VAULT IS ON EAST SIDE OF WALL - SNAPPED OFF BUT CONTINUES UNDER CONCRETE TO EAST.</i>		
Context same as:		

Sample No(s): <i>—</i>	Drawing No(s): <i>ISJ (X)</i>
Photo No(s): <i>2722-2736</i>	Sketch/levels overleaf: <input type="checkbox"/>
	Transferred to plan: <input type="checkbox"/>

Compiled by: <i>cn</i>	Date: <i>21/1/15</i>	Checked by: <i>ca/2/15.</i>	Tick when entered in database: <input type="checkbox"/>
---------------------------	-------------------------	--------------------------------	---

Context Number:
334

Level No.s	Level No.s	Level No.s	Level No.s
TBM	TBM	TBM	TBM
B/S	B/S	B/S	B/S
IH 61 .TS.	IH	IH	IH

No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)	No.	F/S	R/L (m OD)
1		13.23									
2		13.14									
3		12.97									
4		11.69									
5		13.01									

EAST FACING SECTION
SECTION

